

8515 29631

DK Vigtig montage- og garantiinformation - Høj slidhastighed**BEMÆRK**

De konstruktionsmæssige valg i denne servopumpe fører til relativ hurtig nedslidning med deraf følgende forurening af olien.

Hvis systemet ikke bliver gennemskyllet korrekt og grundigt før montering af den nye pumpe, vil det resultere i for tidligt pumpe-svigt.

Fejl der skyldes urenheder i olien dækkes IKKE af garantien.

D Wichtige Montage- und Garantieinformation - Hohe Verschleißrate**ACHTUNG**

Diese Anwendung leidet unter einer hohen Verschleißrate, die das Öl verunreinigt.

Wird das System vor dem Einbau einer neuen Pumpe nicht korrekt und gründlich gespült, führt dies zu einem vorzeitigen Ausfall der Pumpe.

Ein durch verunreinigtes Öl verursachtes Versagen wird NICHT von der Garantie gedeckt.

S Viktig monterings- och garantiinformation - Hög nerslitrings-hastighet**OBSERVERA**

Denna lösning har en relativt hög nerslitrings-hastighet som orsakar smuts i oljan.

Om systemet inte blir sköljt igenom korrekt och noggrant innan en ny pump installeras, kommer det att resultera i för tidigt pumpfel.

Fel på grund av smuts i oljan omfattas INTE av garantin.

GB Important fitting and warranty information - High wear rate**ATTENTION**

This application suffers from high wear rate that contaminates the oil.

Failure to flush the system correctly and thoroughly before fitting a new pump will result in premature failure of the pump.

Failure due to contaminated oil is NOT covered by warranty.