

Heat shield on turbine housing must be replaced if necessary

Introduction:


The vehicle manufacturer has fitted a heat shield to the turbine housing of the turbocharger for thermal shielding of neighbouring vehicle parts.

Note:

Not all available versions of this turbocharger are equipped with this heat shield by the turbocharger manufacturer. So that these versions can be used OE-compliant, it is necessary to use this heat protection plate.

Instructions:

If necessary, remove the heat shield from the old part and fit it to the new turbocharger.



Vehicle Manufacturer: BMW

Vehicle: : (E81, E82, E87, E88) 120 d ; (E90, E91, E92, E93) 320 d ; (E60, E61) 520 d ;
(E84) X1 ; (E83, F25) X3

Engine code: N47D20A, N47D20C

Validity: This service information is valid for renewing the turbocharger with

BTS reference: T914870 **BTS-Service-Set-Nr:** T981026

Please note: OE-references are only for means of comparison. The content of this Service Information is non-binding and is only for informational purposes. The manufacturer specifications have to be adhered to.