



INA Service Info



Pulse sensor 544 0095 10

Damage during removal

Manufacturer: Citroën, Fiat, Ford, Jaguar, Peugeot

Models:

Citroën : C4, C5, C8
 Fiat: Scudo
 Ford: Grand C-Max, Mondeo
 Jaguar: XF
 Peugeot: 508, 807

Engines: 2.0 Diesel, 2.2 Diesel

Part no.: 544 0095 10

For current listing refer to parts catalogue

The pulse sensor for the engine management system (Fig 1.) is made of different material to the crankshaft vibration damper which may lead to corrosion between the parts.



Fig. 1: 544 0095 10 – Pulse sensor for engine management

Because of this in most cases the part is damaged during removal and should therefore be replaced each time it is removed.

During installation of the crankshaft vibration damper, the specified tightening torque of the vehicle manufacturer must be observed.



Fig. 2: Pulse sensor and crankshaft vibration damper

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264
 Fax: +44 (0) 1432 375 760
 aftermarket.uk@schaeffler.com
 www.repxpert.co.uk