

SWAG 30 93 8238

SWAG®

To Fit:
Various Volkswagen, Audi, Seat,
Skoda and Mitsubishi models



EN

Crankshaft Oil Seal

Problem

Oil leak after replacement of the crankshaft seal.

Cause

When installing this sensitive seal, the sealing lip is easily damaged and the seal does not function correctly.

Solution

The SWAG 30 93 8238 crankshaft seal comes complete with a special installation adapter. This is provided to avoid damage to the seal during installation.

For more technical information please visit: partsfinder.bilsteingroup.com