

Turbocharger with different designs on the compressor housing


Introduction:

The vehicle manufacturer used two identically constructed turbocharger with different compressor housings in its serial production. Vehicle data available from the manufacturer to purchase the right spare part are insufficient as these turbochargers have both been used continuously.


Info:

Please compare the manufacturer part number on the old turbocharger with the one on the turbocharger you ordered before you start installing the part or fill the new turbocharger with our additive.

Comparison of manufacturer part numbers:



T912313 MFD 49189-01800
 MFD 49189-01820



T916458 MFD 49189-01810
 MFD 49189-01830
 MFD 49189-01850

Vehicle Manufacturer: SAAB

Vehicle: Saab 9-3, Saab 9-5 2.0 t, 2.3 t / BioPower

Engine code: B205R, B235R

Validity: This service information is valid for renewing the turbocharger with

BTS reference: T912313, T916458 **BTS-Service-Set-Nr:** T981382, T981383

OE-no.: 55559825, 9172180, 55560601, 55561884, 55564966

Manufacturer part no.: 49189-01800, 49189-01820, 49189-01810, 49189-01830, 49189-01850

Please note: OE-references are only for means of comparison. The content of this Service Information is non-binding and is only for informational purposes. The manufacturer specifications have to be adhered to.