



TECHNICAL BULLETIN TECH-03-2021

VW 2.0L - 830324-5004S TURBOCHARGER REPLACEMENT

12TH MARCH 2021

Garrett
ADVANCING MOTION


VW 2.0L - 830324-5004S TURBOCHARGER REPLACEMENT

Dear Customer,

Please note, that production of turbocharger 04L 253 020 G / 830324-5004S was stopped.

As a replacement is available turbocharger 04L 253 014 H / 873732-5001S, which is not a direct service replacement for 830324-5004S.

- There is a different position of the flange for EGR pipe on turbine housing – see below



To replace turbocharger 830324-5004S to be ordered following:


- From Garrett - Turbocharger 873732-5001S
- From franchised VW dealer
 - EGR pipe
 - Gaskets
 - Heatshield
 - Necessary fasteners



VW 2.0L - 830324-5004S TURBOCHARGER REPLACEMENT

Parts to be ordered from franchised VW dealer

- EGR pipe
- Gaskets
- Heatshield
- Necessary fasteners



Please distribute this information to all in your company who may need it.

Best Regards,
Arnošt Pátík
IAM Senior Technical support Specialist
Garrett – Advancing Motion

