



FAG Service Info



Truck Hub Unit (THU)

Observe installation orientation

Manufacturers: DAF, Iveco, MAN,
Mercedes-Benz, Scania, Volvo
Dana, Gigant

Part No.: 201050
571762.01.H195
803194.26.H195
805003A.H195
805003CA.H195
805011.03.H195
805012.06.H195
805092.07.H195

The bearing units listed above must be installed in the correct orientation. Although this is determined by the shape of the axle journal and by the shape of the bearing inner ring of the THU, this Service Info is provided for further clarification.



Fig 1: Truck Hub Unit with seal ring (left) and beveled edge (right) on the bearing inner ring

The key difference can be seen on the bearing inner ring. Some bearing units have an o-ring (Fig. 2) on the inner face, where other bearings have a beveled or rounded edge (Fig. 3). The following table lists the feature and the installation orientation of the bearing units.



Fig 2: Truck Hub Unit with o-ring

Article number	Feature / installation orientation
805003CA.H195 805011.03.H195 805012.06.H195 805092.07.H195	o-ring / faces inward
201050 571762.01.H195 803194.26.H195 805003A.H195	Beveled edge / faces inward



Fig 3: Truck Hub Unit with beveled edge

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264
Fax: +44 (0) 1432 375 760
aftermarket.uk@schaeffler.com
www.repxpert.co.uk

SCHAEFFLER
REPXPPERT