



FAG Service Info



805532.01.H195 and 805532.03.H195

Same bearing, different applications

Manufacturer: DANA
VDL
Renault
DAF

Part no. Truck Axle Module (TAM):
805532.01.H195
805532.03.H195

See parts catalogue for current assignment

The above vehicle and axle manufacturers use Truck Axle Modules (TAMs). When a TAM is replaced, it is important to ensure that the assignment is correct.

Item number 805532.01.H195 is for DANA (axles) and VDL (buses) applications, while item number 805532.03.H195 is for Renault and DAF applications.

Even though the two TAMs look virtually identical to each other, you can still see that one wheel bearing module has a seal installed while the other has no seal.

Technical background:

For Renault and DAF applications, a hub cap must be fitted to complete the repair. This hub cap seals the wheel bearing module.

For DANA and VDL applications, no hub cap is fitted. The seal is already pre-assembled for this reason.

The bearing pressed into the module is identical in both variants (basic no.: F-805531). It is therefore easy to get confused if you pay attention only to the bearing identifier.



Image 1: Item no. 805532.01.H195 has a seal.



Image 2: Item no. 805532.03.H195 has no seal. The seal is provided by the hub cap.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk