



## INA Service Info



# Belt tensioner 534 0314 10

## Tensioning arm with integrated vibration damper

Manufacturer: Citroën

Models: C2, C3

Engines: 1.4 16V

Part no.: 534 0314 10 (new)  
533 0090 10 (replaced)

OE number: 5751.E0  
5751.E1  
5751.H2  
9656150280




Photo 1: 534 0314 10 – Belt tensioner for V-ribbed belts



Photo 2: 533 0090 10 – Vibration damper

Belt tensioner 533 0090 10 (fig. 2) and the accompanying roller of the tensioning arm are subject to the same wear. Therefore from a technical point of view, it makes sense to replace both components at the same time. For that reason, Schaeffler Automotive Aftermarket offers belt tensioner 534 0314 10 (fig. 1) only as a complete assembly.

Vibration damper 533 0090 10 (fig. 2) is no longer available separately.

Please observe the vehicle manufacturer specifications!

**You want more? We can help!**

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER  
**REPXP**PERT