

FAN CLUTCH

Mercedes ACTROS


- >Very simple service of the fan clutch
- >Lower replacement costs
- >No electronic faults

NRF 49021

NRF # 49021
AD. 5412000122
AD. 5412000222
AD. 5412000322
AD. 5412000422
AD. 5412000522
AD. 5412000622

ASSEMBLY MANUAL

1. Remove the electronic fan clutch.
2. Assemble the fan on the bimetallic clutch, using the six bolts M8.
(recommended tightening torque 25 [Nm])
3. If the vehicle is not equipped with a fan clutch flange *, it must be purchased (not included in the set).
4. Assemble the bimetallic fan clutch to the flange using six bolts M8.
(recommended tightening torque 50 [Nm])
5. Using the diagnostic interface, change the fan clutch type in the engine control unit (ECU) to: "Not controlled".



* Fan clutch flange
(OE: **A5410350914**)

Required for installation of the bimetallic fan clutch
(not included in the set)