


# Product Awareness

## Timing Belt Kits

### Hydraulic Damper T1234



**T1234**

To ensure long term performance and reliability, FAI recommend that the damper should be replaced every time the timing belt/kit is replaced.

Not renewing the hydraulic damper could allow a reduction in consistent tension, allowing the belt to move outside of its specified tolerances. Increasing noise during operation and possibly reducing product longevity.



**TBK85**



Make & Model	Year
CITROËN RELAY (230L) 2.8 D	01.99 - 02.02
FIAT DUCATO (230_) 2.5 & 2.8 TD	03.94 - 04.02
FIAT DUCATO (290_) 2.5 TD	07.90 - 03.94
IVECO DAILY I 2.5 TD	01.85 - 12.89
IVECO DAILY II 2.5 & 2.8 TD	01.89 - 08.98
IVECO DAILY III 2.8 TD	05.99 - 07.07
PEUGEOT BOXER (230L) 2.8 D	01.99 - 02.02
RENAULT MASTER 2,5 TD	08.89 - 07.98



**Best Availability. Best Value.**  
**Best Quality. Best Service.**

PA0018



+44 (0) 1525 351800



[faiauto.com](http://faiauto.com)