



TB1071

LuK Service Info

Part Nr. 500 1034 20

Manufacturer: AEBI, CLAAS, EICHER, JOHN DEERE

Art.-Nr.: 500 1034 20

500 1034 20 replaces / ersetzt / remplace / sustituye a / sostituisce 500 0125 20



500 0125 20



500 1034 20

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT