



LuK Service Info Part Nr. 228 0154 10 – 280/280MM TGU6



TB1430

Manufacturer: LANDINI, MASSEY FERGUSON, McCORMICK

LANDINI – 50V, 55V, 5860R, 5865 EVOLUTION, 60V, 6060, 6560V, BLIZZARD

50, 60, POWERFARM 60, 65 75, 90HC, REX 60, 60F, 65F, 65GE, 75F,
75GE, TREKKER C55F, C60F

MASSEY FERGUSON – 353, 354, 356, 363, 364, 366

McCORMICK – C60 MAX, F60, V60, V65

Art.-Nr.: 228 0154 10

**Info: 628 3078 09 replaces / ersetzt
/ remplace / sustituye a / sostituisce
228 0154 10**



628 3078 09 = 228 0154 10 + 328 0083 16

**628 30787 10 = 228 0154 10 + 328 0083 16 + 500 0459 00 + 500 1107 40 + 410
0042 40**



**228 0154 10
OE 6510 441 M91**



**628 3078 09
OE 3671 892M91**



**411 0033 11
Hex Bolt Set M8 x 45 x 1.25 + Conical Washer**

Call : +44 (0) 1432 264264
aftermarket.schaeffler.com

SCHAEFFLER
REP>XPERT