



## LuK Service Info



# Part Nr: 228 0072 10 — 280mm TGU6

Manufacturer: STEYR

Model: 8055, 8060N & 8070N

Art.-Nr.: **228 0072 10**

Info:

New design/Neues Design/Nouvelle conception/Nuevo diseño/Nuovo disegno

228 0072 10 replaces/ersetzt/  
remplace/sustituye a/sostituisce  
228 0072 21



**628 1385 09** = 228 0072 10 + 328 0108 10

**628 1385 10** = 228 0072 10 + 328 0108 10 + 500 0059 10 + 410 0020 40



Bolts 6 x M8 x 1.25 x 50mm are supplied to fit new LuK clutch 228 0072 10.



Schrauben 6 x M8 x 1.25 x 50mm passend für die neue LuK-Kupplung 228 0072 10.



Les boulons 6 x M8 x 1.25 x 50mm sont fournis pour s'adapter au nouvel embrayage LuK 228 0072 10.



Los tornillos 6 x M8 x 1.25 x 50mm se distribuyen para el nuevo modelo de embrague LuK 228 0072 10.




Bulloni 6 x M8 x 1.25 x 50mm in dotazione per la nuova frizione LuK 228 0072 10.



**228 0072 21**

**228 0072 10**



**228 0072 10**

- For accurate model information please see LuK catalogue
- Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog
- Pour plus d'information sur les applications veuillez vous référer au catalogue LuK
- Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK
- Per informazioni sul modello consultare il catalogo LuK

**You want more? We can help!**

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repexpert.co.uk

SCHAEFFLER  
**REP>XPERT**