

8515 16659

**DK** **Vigtig montage- og garantiinformation****BEMÆRK**

Denne servopumpe driver motorens vandpumpe. Enhver skade på vandpumpens leje eller lækage kan beskadige servopumpen og dækkes ikke af garantien.

Vi anbefaler derfor udskiftning af vandpumpen (O.E.: 1477444) (Triscan: 8600 16019).

**D** **Wichtige Montage- und Garantieinformation****ACHTUNG**

Bei diesem Fahrzeug sind die Servo- und Wasserpumpe Teil des gleichen Antriebs. Jegliche Beschädigung oder Undichtheit des Wasserpumpenlagers führt zu einem vorzeitigen Ausfall der Lenkungspumpe, die nicht von der Garantie abgedeckt ist.

Wir empfehlen dringend, Ihre Wasserpumpe zu ersetzen (O.E.: 1477444) (Triscan: 8600 16019).

**S** **Viktig monterings- och garantiinformation****OBSERVERA**

Denna servopump driver motors vattenpump. En skada på vattenpumpens lager eller läckage kommer att orsaka för tidigt fel på servopumpen, som inte omfattas av garantin.

Vi rekommenderar starkt att byta ut vattenpumpen (O.E.: 1477444) (Triscan: 8600 16019).

**GB** **Important fitting and warranty information****ATTENTION**

This steering pump drives the engine water pump. Any damage to the water pump bearing or leaking will cause premature failure of the steering pump, not covered by warranty.

We strongly suggest replacing your water pump (O.E.: 1477444) (Triscan: 8600 16019).



OE Ref.: 1477444 Vandpumpe/Wasserpumpe/Vattenpump/Water pump (Triscan: 8600 16019)