

## Camshaft Tightening Procedure Procedimiento de Apriete de Árboles de Levas

93085100	MAKE MARCA	ENGINE MOTOR	CAMSHAFT PINION TIGHTENING APRIETE PIÑÓN ÁRBOL LEVAS	CAMSHAFT BEARING TIGHTENING APRIETE COJINETE DEL ÁRBOL
Kilos	MERCEDES MERCEDES	MB111.920/940/941 MB111.942	2 Kpm + 90°	2 Kpm
Libras	MERCEDES MERCEDES	MB111.920/940/941 MB111.942	15 lbft + 90°	15 lbft

AJUSA IS NOT RESPONSIBLE FOR ANY UPGRADE AFTER THIS DOCUMENT HAD BEEN PRINTED. FOR MORE INFO, PLEASE VISIT OUR WEBSITE [www.ajusa.es](http://www.ajusa.es)

AJUSA NO SE RESPONSABILIZA DE CUALQUIER ACTUALIZACIÓN POSTERIOR A LA IMPRESIÓN DE ESTE DOCUMENTO. PARA MAYOR INFORMACIÓN VISITE NUESTRA PAGINA WEB [www.ajusa.es](http://www.ajusa.es)