

This new version replaces all previous versions. Please replace SI-121215
Changed connection on compressor outlet

Please note :

If one of the following old OE or manufacturer references (picture 1) **03L253019A, 03L253019T** or **53039700132, 53039880132** or the old version of muffler is installed (picture 3), a muffler kit **D950072** (picture 4) has to be used additionally, in order to install the new turbocharger **T915508** (picture 2) 53039880205, 03L253056A!

If any of the following OE or manufacturer references are installed, the old muffler can be used: 03L253019J, 03L253016F, 03L253010C or 53039700139, 530398800139

Please still check the old muffler for any damages or dirt contamination. If necessary, D950072 may be used as a suiting spare part.



picture 1
old manufacturer number



picture 2
T915508 current version



picture 3
old version of muffler



picture 4
new muffler D950072

Vehicle manufacturer: VW, AUDI, SEAT, SKODA

Vehicles: Passat, Jetta, Golf, Scirocco, Tiguan, A3, YETI, ETOS

Engine Code: CBAA, CBAB, CBAC, CBDA, CBDB, CBDC

Validity: This service information is valid for the exchange of the turbocharger with

BTS reference.: T915508

OE reference: 03L253010C, 03L253016F, 03L253019A, 03L253019J, 03L253019T, 03L253056A

Manufacturer reference: 53039700132, 53039700139, 53039700205, 53039880132, 53039880139, 53039880205

OE-references are only for means of comparison.

The content of this Service Information is non-binding and is only for informational purposes.

The manufacturer specifications have to be adhered to.