



TRACTOR SERVICE INFO




TB2072

Part Nr. 532 0943 10 / 532 0944 10 - Feed Pulley

CNH – T7.220 AUTOCOMMAND, T7.235 AUTOCOMMAND, T7.250

AUTOCOMMAND, T7.260 AUTOCOMMAND, T7.270 AUTOCOMMAND

T7.220, T7.235, T7.250, T7.260, T7030, T7040, T7050, T7060



BOLT – 90MM

532 0943 10
OEM – 504088268 / 87300114



BOLT – 110MM

532 0944 10
OEM – 504088269 / 87300115

