



LuK Service Info



TB1172

Part Nr. 500 1350 10 - PTO BEARING

Manufacturer: SAME

Model: CORSARO 70 FRUTTETO
 CORSARO 70 SYNCHRO
 FALCON 50
 MINITAURO 60 FRUTTETO
 MINITAURUS 60 FRUTTETO
 MINITAURUS 60 SYNCHRO
 TAURUS 60
 VIGNERON 70

Art.-Nr.: 500 1350 10

New product / Neues Produkt /
Nouveau produit / Nuevo producto
/ Nuovo prodotto



OEM 2.2040.019.0

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT