



TB1229

LuK Service Info

Part Nr. 631 3161 10 - 310/301 TGU6

Manufacturer: LANDINI, MASSEY FERGUSON


Model: 1000/S, 1000 & 1014

Art.-Nr.: 631 3161 10

New product / Neues Produkt /
Produit Nouveau / Nuevo Producto
/ Nuovo Prodotto



631 3161 10 = 231 0030 10 + 331 0097 16 + 500 0076 11 + 500 0217 40 + 410 0154 40



Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT