

Problem solved: New versions of Golf IV door locks now available

A change of construction design means that problems previously encountered with the installation of original door locks for the Golf IV have now been remedied. These modified locks are now also additionally available from AIC.

Getting the right combination for the various applications can be a little tricky, however. **Find the right combination for every vehicle here:**

The current catalogue data already incorporates the linkages to the respective vehicles, and all new locks are immediately available and on stock.


	FL	FR	BL	BR
Arosa	50628	50629		
Leon	50628	50629	52973	52974
Toledo II	50628	50629	52973	52974
Octavia (1U2/1U5)	50628	50629	52973	52974
Bora until 08.2001	50628	50629	52973	52974
Bora from model 2002	55271	55272	55273	55274
Lupo	50628	50629		
New Beetle until model year 2005	50628	50629		
New Beetle from model year 2006	55271	55272		
Golf IV	55271	55272	52973	52974
Passat (3B2/3B5)	50628	50629	52973	52974
Passat (3B3/3B6)	50628	50629	55273	55274
T5 until model year 2009		55272		

Table 1:

Usage on vehicles of both door lock series. **Red text** denotes the changes to applications until now.

Item no. 50628 ff.:

The previous series remains in the range, only some applications have changed. This applies to the models Golf IV, Passat and New Beetle.



AIC-Artikel-Nr.	50628	50629	52973	52974
Installation	FL	FR	BL	BR
OE references	3B1 837 015A 6X1 837 013A 6X1 837 013H 6X1 837 013C	3B1 837 016A 6X1 837 014A 6X1 837 014H	3B4 839 015A	3B4 839 016A

Item no.. 55271 ff.:

This series replaces some of the previously used locks for Golf IV, Passat (383/386) and New Beetle.




AIC-Artikel-Nr.	55271	55272	55273	55274
Installation	FL	FR	BL	BR
OE references	3B1 837 015AK 3B1 837 015AS 3B1 837 015J	3B1 837 016BH 3B1 837 016CF 3B1 837 016R	3B4 839 015AM	3B4 839 016AM



ATTENTION



NOTES FOR INSTALLATION



IF IN DOUBT

Both groups of article numbers are now active: only the application changes partly (see **red highlighted text** in table 1, above)

- Please observe the vehicle manufacturer's instructions

Please take note of the details contained in application table 1