

# RepCab


## Repair Set, harness

Manufacturer:

BMW

Model:

5

Fitting Position	Construction year	Design	Conductor Number conductor	Cable Length mm	DU	Article no.
Vehicle Tailgate Left Vehicle Rear Windscreen	2004/06 to /	with wash water pipe with antenna cable with isolation tape with squeeze connector with bellow	15	1250	 1	51277246
<b>Accessories</b>				see	DU	
Cable stripper Stripper				Katalog08	1	95942326
Crimping Pliers Insert				Katalog08	1	95942347
Crimping Pliers CrimPro 10				Katalog08	1	95942330
				Katalog08	1	95942331



with double bush



all plug housings fully assembled