


KABELLÖSUNG

Neu bei METZGER:
Ölstopp-Kabel für Anschlussleitung
Nockenwellenversteller Mercedes-Benz: A 271 150 27 33

Innovation: Ölstopp-Steuerungsverbinder Ölindikator-Litze

„Verbesserte
Version“

Der Ölverlust am Nockenwellenversteller ist bei bestimmten Mercedes-Benz Motoren ein bekanntes Problem. Durch die Kapillarwirkung kann das Öl im Kabelbaum bis zum Steuergerät gelangen. Dies kann zum Ausfall der Elektronik führen. Durch das Metzger „Ölstoppkabel“ wird ein Eindringen von Öl in den Kabelbaum wirksam verhindert.



Ölstopp-Steuerungsverbinder

- Korrosionsfrei
- Verbindungstechnologie gemäß
 - Norm DIN EN 60352-2
 - VW Norm Group Standard VW 60330

METZGER Artikelnummer: 2324048



OE-Nummern dienen nur zu Vergleichszwecken



Werner Metzger GmbH Telefon +49 711 / 160 86 - 0
Rita-Maiburg-Str. 33 Telefax +49 711 / 160 86 - 86
D-70794 Filderstadt E-mail info@werner-metzger.de

www.werner-metzger.de

CABLE SOLUTION

New at METZGER:

Oil stop cable for connecting lead camshaft adjuster
Mercedes Benz: A 271 150 27 33


Innovation:

Oil stop line connector

Oil indicator stranded wire

„Improved
Version“

The loss of oil at the camshaft adjuster is a known problem with certain Mercedes-Benz engines. Due to the capillary effect, the oil in the wiring harness can reach the control unit. This can lead to failure of the electronics. The Metzger's „oil stop cable“ effectively prevents oil from penetrating the wiring harness.



Oil stop line connector

- Corrosion-free
- Connection technology according to
 - Standard DIN EN 60352-2
 - VW Norm Group Standard VW 60330

Part number 2324048



OE numbers are for comparison purposes only



Werner Metzger GmbH
Rita-Maiburg-Str. 33
D-70794 Filderstadt

phone +49 711 / 160 86 - 21
fax +49 711 / 160 86 - 86

E-mail export@werner-metzger.com

www.werner-metzger.com