

SI-160214

Service Information Turbolader

Changed connection on compressor outlet

Please note:

If one of the following old OE or manufacturer references (picture 1) 03L145702, 03L145702J or **53039700131, 53039880131** or the old version of muffler is installed (picture 3), a muffler kit **D950072** (picture 4) has to be used additionally,

in order to install the new turbocharger T914995 (picture 2) 53039880189, 03L145701E!

If any of the following OE or manufacturer references are installed, the old muffler can be used: 03L145702E, 03L145701A or 03L145702E, 03L145701A.

Please still check the old muffler for any damages or dirt contamination. If necessary, D950072 may be used as a suiting spare part.



picture 1 old manufacturer number



old version of muffler



picture 2 T914995 current version



Vehicle manufacturer: VW

Vehicles: currently no known data Engine Code: currently no known data

Validity: This service information is valid for the exchange of the turbocharger with

BTS reference.: T914995

OE reference: 03L145701A, 03L145701C, 03L145701E, 03L145702, 03L145702E, 03L145702J, 03L145702N,

03L145702V, 03L145702X

Manufacturer reference: 53039700131, 53039700138, 53039700189, 53039710138, 53039880131,

53039880138, 53039880189

OE-references are only for means of comparison.

The content of this Service Information is non-binding and is only for informational purposes. The manufacturer specifications have to be adhered to.



